

12. Welding

*For inquiries and questions about welding, refer to ;

<http://www.rcnp.osaka-u.ac.jp/Divisions/safety/english/related.pdf>

- A license and applicable qualifications are necessary for welding work
- Appropriate fire-prevention measures must be taken, and a fire extinguisher must be present for any welding work.

< General Information >

- (1) Any person welding metal using flammable gases and oxygen needs a license for gas welding or proof of successful completion of a gas-welding skills course.
- (2) On welding work, please assess the situation around the work space (ex. Whether or not there are flammable gasses, inflammables and machinery.) yourself. If necessary, you must take measures for fire prevention as well as prevention of damage to machinery caused by welding. In addition, please confirm that a fire extinguisher is nearby before beginning any welding work. If no fire extinguisher is present, you must take measures to ensure that one is present.